

ONESTEEL REINFORCING

2015 ALC
Supply Chain Safety &
Compliance Summit

Back of Vehicle Height Safety

Jason McMartin



onesteel reinforcing


Back of Vehicle Height Safety

- The problem
- History



onesteel reinforcing

First Attempt



Gates Chained together

Right Angle Edges

Gaps

Fatigue Points

Stability of Gates

onesteel reinforcing

What Good Looks Like

Back of Vehicle Height Safety Standard ??


- Hand railing Aust Std
- Top rail 0.900 min to 1.100 max
- Intermediate 0.450 max



onesteel reinforcing


Spacing's

- 0.930 from top of container
- 0.630 from top of container
- 0.340 from top of container
- 0.630 to top of container to trailer deck



onesteel reinforcing

Span Set - Web Rail



onesteel reinforcing

Span Set - Web Rail

onesteel



SpanSet
WebRail
Heavy Vehicle Exit Protection

onesteel reinforcing

Suit Both Rigid Vehicles & Trailers


onesteel



onesteel
reinforcing

Non Obtrusive


onesteel



onesteel
reinforcing

Questions

onesteel



onesteel
reinforcing